

FIG. 1







FIG. 2





FUG. 4






FIG. 6

(TABLE 3)

COMPARE AND THEN CHECK LINE NAMES	PARTS TYPES	SIZE	MANUAL NUMBERING
В	С	D	0
B'	C'	D'	

FIG. 7

(TABLE 11A)

PARTS NUMBER	COMPARE AND THEN CHECK LINE NAMES	PARTS SPECIFICATION	NUMBER OF PARTS
	В	E	F
	В'	E	G

FIG. 8A

(TABLE 11B)

PARTS	COMPARE AND THEN CHECK LINE NAMES	PARTS	NUMBER OF
NUMBER		SPECIFICATION	PARTS
	(-)	E	F + G

FIG. 8B

(TABLE 11C)

· · · · · · · · · · · · · · · · · · ·			
PARTS NUMBER	COMPARE AND THEN CHECK LINE NAMES & PARTS SPECIFICATION	NUMBER OF Parts	PARENT-CHILD RELATIONSHIP
Α	В	E	PARENT
A' B'		F	PARENT

FIG. 9A

(TABLE 11D)

PARTS NUMBER	COMPARE AND THEN CHECK LINE NAMES & PARTS SPECIFICATION	NUMBER OF PARTS	PARENT-CHILD RELATIONSHIP
Α	A B		PARENT
A B'		F	CHILD

(TABLE 11D)

PARTS	COMPARE AND THEN CHECK LINE NAMES	NUMBER OF
NUMBER	& PARTS SPECIFICATION	PARTS
Α	В	E+F




FIG. 10

(TABLE 3)

COMPARE AND THEN CHECK LINE NAMES	PARTS TYPES	SIZE	CONSIDERATION OF YIELD RATE
В	С	D	0
B'	C'	D'	

FIG. 11




FIG. 12